INSPECTION REPORT

Partial XXX Complete ___Exploration ___ Inspection Date: 08/19/2003 Time: 9:00am-1:30pm Date of Last Inspection: 07/10/2003

Mine Name: Deer Creek Mine	County: Emery	Permit Number: <u>C/015/018</u>				
Permittee and/or Operator's Name: Pac	eifiCorp					
Business Address: P.O. Box 310, Huntington, Utah 84528						
Company Official(s): Dennis Oakley						
State Official(s): Stephen J. Demczak, Jim Smith Federal Official(s): None						
Weather Conditions: Warm, Sunny, 80's						
Type of Mining Activity: Underground XXX Surface Prep Plant Other						
Existing Acreage: Permitted 24,638.5	52 Disturbed <u>95.79</u>	Regraded Seeded				
Status: Active						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS	ĹÌ	\Box	Ĺĺ	Ĺĺ
3.	TOPSOIL	ĹÌ	ĹÌ	Ĺĺ	Ĺĺ
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]	\Box	[X]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	\Box			
c.	OTHER SEDIMENT CONTROL MEASURES	[X]	\Box	[X]	\Box
d.	WATER MONITORING	[X]	\Box	[X] [X]	\Box
e.	EFFLUENT LIMITATIONS				
5.	EXPLOSIVES				
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	\Box			
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS				
8.	NONCOAL WASTE	[X]		[X]	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES				
10.	SLIDES AND OTHER DAMAGE				
11.	CONTEMPORANEOUS RECLAMATION		\Box		
12.	BACKFILLING AND GRADING				
13.	REVEGETATION				
14.	SUBSIDENCE CONTROL			\Box	
15.	CESSATION OF OPERATIONS				
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING				
b.	DRAINAGE CONTROLS	[X]		[X]	
17.	OTHER TRANSPORTATION FACILITIES				
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS			\Box	
19.	AVS CHECK (4 th Quarter- April, May, June)				
20.	AIR QUALITY PERMIT				
21	BONDING & INSURANCE	ГТ	[]	[]	[]

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/015/018</u> DATE OF INSPECTION: <u>08/19/2003</u>

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permittee has legal and financial information outstanding with the Division. This action is addressed as Legal and Financial LF03A.

The permittee has promised to submit an amendment to address the paving of the waste rock road. If an amendment is not submitted to the Division by the next inspection, a Notice of Violation will be issued to the permittee.

4A. HYDROLOGIC BALANCE: DIVERSIONS

Several diversions were inspected. The permittee is in the process of cleaning diversion ditches throughout the property. The mine has received several thunderstorms in the pass week and has filled the diversions within sediment. The culvert drop drain in front of the warehouse is partly plugged with sediment. The permittee has committed in cleaning this inlet in the near future.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Several sediment traps are filled with sediment. This was caused by several afternoon thunderstorms. The permittee has a crew in the process of cleaning out the sediment traps and diversions throughout the property.

4D. HYDROLOGIC BALANCE: WATER MONITORING

Jim Smith from the Division in Salt Lake City reviewed water monitoring with Dennis Oakley. The discussion mainly dealt with the water wells. Some of the information on water depth was in feet and others were in meters. Both parties agreed that the problem is either in the electronic programming or is being entered differently each time. Jim Smith will check out if it is a computer error, and the permittee will pay better attention on entering the data.

8. NONCOAL WASTE

The mine site was clear of non-coal waste material

16B. ROADS: DRAINAGE CONTROLS

The diversion ditches along the main road from the county road has started to erode. If this continues, this could undercut the main primary road to the mine. The permittee has stated that the diversions ditches will be reconstructed as designed.

Inspector's Signature: _			Date:	August 20, 2003
-	Stephen J. Demczak	#39		

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Chuck Semborski, PacifiCorp, via email
Price Field office
O:\015018.DER\Compliance\2003\p_0819.doc